

Providing

C CRANE SERVICES.
H HEIGHT SAFETY.
L LIFTING SERVICES.
E ENGINEERING.

Lifting Gear Inspection Report

Job No:	24-0031
Page No	
Client Order/Purchase No:	
Date:	Start: 02-Feb-24 Finish: 12-Mar-24
Site:	Multipule

<u>Inspectors</u>	
N Thompson	NT
D Simpkins	DS
C Bisa	CB

Dianneil Pty Ltd. t/as CHLE
 ABN: 73 619 705 190
 PO Box 454, Mitchell, ACT 2911
 Ph: (02) 6255 5741
 Email: chlesales@chle.com.au

Client name: ... **RAR CRANES**
 Address:..... 36 Bedford street
 Queanbeyan NSW 2620
 Contact:..... Richard Garrety
 Email:..... richard@rargroup.com.au
 Mob: 0405 991 935

NOTE: The Next Inspection Due Date is a Maximum Date Due. The inspection schedule has to be determined by the end user based on the duty cycle (of M3 as specified in AS1418.1) and the environmental conditions of use

Location	Asset	Inspection Date	Serial No	Description	Manufacturer	WLL	Inspected IAW: AS	Passed	Failed	Missing	Repaired	Condemned	Inspector	Next Inspection Due	Comments
910		13-Feb-24	P1919	G100 10mm x 8M 2Leg chain sling c/w clevis grab and safety hooks	Allways Rigging Gear	6.9t @ 60°	AS 3775	YES					CB	13-Feb-25	
910		13-Feb-24	P2041	G100 10mm x 8M 2Leg chain sling c/w clevis grab and safety hooks	Allways Rigging Gear	6.9t @ 60°	AS 3775	YES					CB	13-Feb-25	
910		13-Feb-24	P2011	G100 16mm x 8M 2Leg chain sling c/w clevis grab and safety hooks	Allways Rigging Gear	6.9t @ 60°	AS 3775	YES					CB	13-Feb-25	
910		13-Feb-24	P2040	G100 16mm x 8M 2Leg chain sling c/w clevis grab and safety hooks	Allways Rigging Gear	6.9t @ 60°	AS 3775	YES					CB	13-Feb-25	
910		13-Feb-24	R0735	G80 10mm x 6M 2Leg chain sling c/w eye grab and clevis safety hooks	Ranger	5.5t @ 60°	AS 3775	YES					CB	13-Feb-25	
910		13-Feb-24	24685	G80 16mm x 8M 2Leg chain sling c/w clevis grab and safety hooks	Stenhouse	13.8t @ 60°	AS 3775	YES		TAG			CB	13-Feb-25	